

LONGVIEW FIBRE COMPANY

MAIN OFFICE AND MILLS. LONGVIEW, WASHINGTON 98632

P. O. Box 667

November 17, 1969



County Surveyor
Tillamook County Courthouse
Tillamook, Oregon 97141

Dear Sir:

Enclosed please find a copy of our office record of corner information as assembled and noted by this Company. This information is forwarded in keeping with a policy of this Company to furnish corner information in a readily accessible book form.

As additional sheets and additions to these sheets are forwarded to you, may we suggest that you remove your old copy sheet and replace it with the more recent. This will serve not only in keeping you up to date but will avoid unnecessary pages in your loose-leaf book.

The corner information on these record copies has been assembled by this Company and almost without exception, pertains to corners referenced, established, or restored by this Company.

If you have any questions regarding this information, please contact this office.

Very truly yours,

A handwritten signature in cursive script, appearing to read "O. R. Miller".

O. R. Miller
Forest Engineer

db

enc

TOWNSHIP 3 SOUTH, RANGE 9 WEST

Section Corner, Sections $\frac{24}{19}$, T3S, R9W and 10W
 $\frac{25}{30}$

Found $1\frac{1}{2}$ " iron pipe with Oregon State Board of Forestry brass cap, for corner.

"1958 - RS 401"

From which I found the following BT's:

12" Spruce bears N 57° W 1.4 feet

20" D. Fir snag bears N 52° W 127.0 feet

2

Also found white guard post with #465.

Corner sets approximately 75' north of Bunn Creek.

Corner sets 15' south of dirt road to Longview Fibre Co. property.

July, 1969

Found by: Stan Benson, LFCo.

NW 1/16 Corner, Section 30, T3S, R9W

Found $1\frac{1}{2}$ " iron pipe with brass cap for corner, marked as follows:

"Oregon State Board of Forestry
 NW 1/16 S30 - 1958"

Found white post with number "488" - 1 tag - no B.T.

2

Corner lies on N.E. slope, approximately 100' east of N-S ridge.

July, 1969

Found by: Stan Benson, LFCo.