


CERTIFIED RECORD OF LAND CORNER MONUMENT

History of original corner establishment:

Corner originally set by Henry Meldrum in 1879. In 1949 Anderson set a 1 1/2" iron pipe and scribed 2 willow BTs. In 1956 2 2" pipes were set as accessories. Carlich found remains of Willow stump and 2 2" accessory pipes plus the corner pipe.




Description of corner evidence found:

Found a 1 1/2" iron pipe buried 4" on edge of highway 101. from which
 A 2" pipe brs. N8W 48.0 ft
 A 2" pipe brs. S23W 32.1 ft

Description of monument and accessories I established to perpetuate the original location of this corner

Set a 2"x30" iron pipe with brass cap marked



1970
920

Because of difficulty of removing old pipe and resetting brass cap in asphalt, I left old pipe in place and set brass cap as witness to true corner 13.9 ft due south

Set steel fence post 2 1/2 ft due east of brass cap with attention sign facing north.

Office of COUNTY SURVEYOR County of TILLAMOOK
 State of OREGON, I hereby certify that the within instrument was filed in this office
 for record on the 9th day of SEPTEMBER, 1970, at o'clock m., (signed)
[Signature] C. SURVEYOR by (DEPUTY)

REGISTERED
OREGON
LAND SURVEYOR

[Signature]
 JULY 17, 1970
 RICHARD L. BRYANT
 920