

County Surveyor's Record, Tillamook County, Oregon

CHAINS

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 19 and 20, T1S, R8W, W.M., Tillamook County, Oregon

REESTABLISHMENT by United States Cadastral Surveyors (1958)

2" iron pipe with brass cap (found in place, cap marked T1S R8W 1/4 S19 S20 1958) from which a:

15" Hemlock bears N.44-1/2°W. 133 lks. now 22"; scribes mostly grown over.

26" Hemlock bears N.19-1/4 E. 97-1/2 lks.; now 26" stump, uprooted out of position.

REWITNESSED

VAR. 21-1/2 E.

From above pipe and cap:

11" Hemlock bears S.63°E. 34.9 ft.; scribed 1/4 S20 BT RS707.

Road bears North 53 ft. N85°E. by S.70°W.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. SE of corner pipe. Oregon State Forestry Department metal location poster on 11" Hemlock BT.

Dated May 19, 1970

Rewitnessed by

Present and witnessed by L. Carver

REGISTERED
OREGON
LAND SURVEYOR

Harold J. Russell
JULY 9, 1955
HAROLD J. RUSSELL
707