

CHAINS RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 7 and 8, T2N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

34" Cedar bears N.88°W. 20 lks.; now a 40" dead cedar, backcast face visible, face cut out and burned. Cruiser mark on south side.

3" Hemlock bears N.57°E. 5 lks.; missing.

RESTORED

Var. 21-1/2°E.

Set 1-1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S7 S8 1970 RS401", 33 inches in ground, from which a:

10" Fir bears N.72-1/2°E. 5.5 ft.; scribed 1/4 S8 BT RS 401.


11" Fir bears N.33°W. 13.0 ft.; scribed 1/4 S7 BT

Set 4" x 4" x 50" white painted Cedar post 1.0 ft. S.E. of corner pipe. Oregon State Forestry Department metal location poster on 10" Fir BT.

Dated May 14, 1970

Restored by Charles E. Curl under my direction.
Charles E. Curl, Transitman

Present and witnessed by B. Henderson
A. Tocchine



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401