

County Surveyor's Record, Tillamook County, Oregon

CHAINS

4/3
9/10

165

3/4
10/9

2510

Found All Bearing Trees:
 30" Hem N19W
 Now Rotten Up root ± 59'
 48" Hem N67W 676
 Now 50" Hem Stump Scribing Visible
 72" Spr N32E 765
 Now 74" Spr Stump Scribing Visible
 80" Spr S38W 510
 Now 86" Spr Stump Could Not Find Scribing
 36" Hem S62E 802
 Now 38" Hem Stump Scribing Visible
 Did Not Find 1/2" IP or 4"
 Spr Limb. Car was destroyed
 when Logged, Car Falls in
 Skid Road.
 I set New 2" IP From Bearing
 Trees Calls.

G. Arthur
 S Skinner 4- -66

BOOK 5 10/28/70 J. H. Condit CS