


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

W. E. Anderson set an iron pipe in May 1937




Description of corner evidence found:

Anderson's pipe not found.

Description of monument and accessories established to perpetuate the original location of this corner

Set 2" x 30" galvanized iron pipe flared at the bottom and a brass cap pivoted at the top extending 4" above the ground.

Stamped disk



Set steel post with Forest service signs 5.0 ft west of monument.

New Bearing trees as follows:

9" Alder scribed "5 1/16 54 BT" N49°15'W 47.88 ft.

26" Spruce scribed "5 1/16 54 BT" S3°45'E 10.00 ft.

Placed U.S.F.S. Bearing tree signs on each tree breast high & facing monument.

Office of County Surveyor County of Tillamook  
 State of OREGON, I hereby certify that the within instrument was filed in this office  
 for record on the 20 day of JUNE, 1971, at 9 o'clock A.m., (signed)  
Opal Carlisle by August C. Giering  
 (COUNTY OFFICIAL) (DEPUTY)

REGISTERED  
 OREGON  
 LAND SURVEYOR

August C. Giering  
 JULY 12, 1963  
 AUGUST C. GIERING  
 608

BOOK 5

CLARK & GROFF ENGINEERS, INC.  
 3276 COMMERCIAL STREET S. E.  
 SALEM, OREGON

Form R6-7100-57 (9/66)

BOOK 5

162