


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1882 by General Land office. Contract Survey

Original Survey states "Set Post 4 ft Long 6" in diameter 12" in ground, marked 1/4 50 on north face from which Fir, 6" diam. bears 583°W 90 Lks dist. MKd. 1/4 SBT, Spruce 50" diam bears N30°E 47 Lks mkd. 1/4 SBT




Description of corner evidence found:

Found no evidence of original 1/4 cor.

Description of monument and accessories I established to perpetuate the original location of this corner

Set by proportional measurement a 2" x 30" galvanized iron pipe flared at the bottom and a brass cap riveted on top, extending 4" above the ground.

Set steel post with Forest Service Sign 2.0 ft. west of monument.



New Bearing trees as follows:

16" Fir scribed "1/4 53 BT" N 29°15'W 31.28 ft.

15" Fir scribed "1/4 510 BT" S 39°26'E 12.08 ft.

Placed U.S.F.S. Bearing tree signs on each tree breast high facing monument.

Office of County Surveyor County of TILLAMOOK
 State of OREGON, I hereby certify that the within instrument was filed in this office
 for record on the 16 day of JUNE, 1971, at 9 o'clock A.m., (signed)
[Signature] by [Signature] (DEPUTY)
 (COUNTY OFFICIAL)

REGISTERED
 OREGON
 LAND SURVEYOR

[Signature]
 JULY 12, 1963
 AUGUST C. GIERING
 608

CLARK & GROFF ENGINEERS, INC.
 3276 COMMERCIAL STREET S. E.
 SALEM, OREGON

BOOK 5