

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 13, 18, 19 and 24, Township 3 North, Range 5 and 6 West, W.M., Tillamook and Washington Counties, Oregon.

6 30 5  
13 11 8  
24 11 9

ORIGINAL

Post (now missing) from which a:

- 10" Hemlock bears N45E 20 lks.; missing.
- 10" Hemlock bears S45E 20 lks.; missing.
- 9" Hemlock bears S85W 25 lks.; missing.
- 12" Hemlock bears N80W 15 lks.; missing.

RESTORATION by Lincoln E. Wilkes in 1892 (Original Surveyer - Retracement).

Post (now missing) from which a:

- 50" Fir bears N40 1/2°E 78 lks.; now a 50" stump scribed T3N R5W S18 BT.
- 24" Hemlock bears S62E 72 lks.; missing.
- 8" Hemlock bears S62W 72 lks.; missing.
- 48" Fir bears N36°15'W 36 lks.; now 48" stump with scribes BT visible.

RESTORED

Var. 21 1/2°E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R5&6W S13 S18 S19 S24 1972 RS707", 33 inches in ground, and from which a:

- 11" Fir bears N17 1/2W 1.7 ft. to face; scribed T3N R6W S13 BT RS707.
- 12" Fir bears N45 3/4E 2.7 ft. to face; scribed T3N R5W S18 BT.
- 18" Fir bears S57 1/4E 35.0 ft. to face; scribed T3N R5W S19 BT.
- 9" Fir bears S71 1/2W 17.2 ft. to face; scribed T3N R6W S24 BT.

Set 4" x 4" x 60" Fir post 1.0 ft. N.E. of corner pipe. Oregon State Forestry Department metal location poster on 11" Fir BT.

Dated January 25, 1973

Restored by Loren Steele under my direction.  
Loren Steele, Engineer

Present and witnessed by Steve Ellis

