CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM 1/4 Corner Section 31 T 5 S R 10 W

Reference:

Plat dated July 1973 by -Timberland Services, Inc. under my stamp. B-609

Description of corner evidence found:

Found brasscap marked:

T 5 S R 10 W SC

514 1/4 S 31

1971 RLS 816 From which a:

48" Spruce N. 28° E 74.6 ft. 41" Spruce N. 68° E 45.7 ft.

Description of manument and accessories I established to perpetuate the original location of this corner

I painted the BT's, secured the attention sign, and removed brush from around the monument.

> Witnessed: B. Jones M. Cook

Office of Gonzy Surveyor Country of Truamook

7 day of ANGUST 1973, or 933 o'clock m., (signed) ICOUNTY OFFICIAL!

(DEPUTY)

Found this 28th day of June 1973.

B00K 5

Edgar R Cook

TIMBERLAND SERVICES, INC. P.O. Box 668 - Albany, Ore. 97321 Phone: 928-3539

KENNETH M. WIGHTMAN II 942

REGISTERED

PROFESSIONAL

LAND SURVEYOR

Graduate Forest Engineer Form R6-7100-57 (9/66)