

County Surveyor's Record, Tillamook County, Oregon

CHAINS

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 1 and 2, T2N, R7W, W.M.,
Tillamook County, Oregon.

ORIGINAL

Basalt stone 12" x 12" x 10" (now missing, 1" iron pipe, see below, in place)
from which a:

- 8" Hemlock bears N87°W 32 lks.; now a badly rotted 12" stump with
axe marks visible and a Crown Zellerbach YMLP.
- 10" Hemlock bears N71°E 18 lks.; the BT uprooted leaving a hole in
the slope, now an 18" Hemlock uproot approximately 80' down
a steep slope to the East with an OSBF YMLP and a C.Z. YMLP
on the underside.

RESTORATION by Bert Mason, Jr., October 31, 1956.

1" x 30" galvanized iron pipe with 2" cap 15" in ground, marked T2N R7W 1/4 S2/
S1 1956 LS 322 (in place and in good condition) from which a:

- 36" Fir stump bears S30½°W 23.2 ft.; now a 36" stump with
scribes S2 1/4 S BT visible. The distance is now 24.7 feet.

REWITNESSED

Var. 21½°E

From above corner monument in mound of rock a:

- 5" Fir bears N87°W 8.6 ft. to face; scribed 1/4 S2 BT.
- 6" Fir bears N69½°E 9.2 ft. to face; scribed 1/4 S1 BT RS 707.

Set 4" x 4" x 74" white painted Cedar post 1.0 ft. NE of corner pipe.
Oregon State Forestry Department metal location poster on 6" Fir BT.

Dated December 16, 1974.

Rewitnessed by Loren R. Steele under my direction.
Loren Steele, Forest Engineer

Present and witnessed by Terry Withrow

