

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Center-East One Sixteenth corner for Section 27, T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

OSBF Pipe and Cap, 1959 (missing in road construction) from which a:

44" Hemlock bears S9½°W 106.3 ft.; now 44" x 100' tall snag, scribes CE 1/16 S27 BT visible on open face, with yellow metal location poster on Southwest side.

22" Hemlock bears S60½°E 95.4 ft.; now 22" stub, scribes CE 1/16 S27 BT RS401 visible on open face.

RESTORED

Var. 21½° E.

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY E 1/16 CC S27 1976 RS707", 34 inches in ground, in mound of rock, and from which a:

15" Alder bears N6°W 56.4 ft. to face; scribed in bark CE 1/16 S27 BT RS707.

Graveled road bears South 182.3 ft., course N79°W by S81°E.



Spring branch bears S60½°W 16.0 ft. to center; course N26°E.

Set 4" x 4" x 60" white painted Cedar post 2.4 ft. NE of corner pipe.

Dated June 29, 1976.

Restored by Keith D. Whitehead under my direction.  
Keith D. Whitehead, Transitman

Present and witnessed by Mike Nordin



BOOK 5