

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Center-East One-Sixteenth corner for Section 31, T2S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

OSBF Pipe and Cap, 1966, (Found out of place, disturbed by logging) from which a:

31" Fir bears N29 $\frac{1}{4}$ °E 7.8 ft.; now 31" stump, S61  $\frac{3}{4}$ °E 7.8 ft., bottom tip of face remaining.

27" Fir bears S61  $\frac{3}{4}$ °E 10.8 ft.; now 30", N29 $\frac{1}{4}$ °E 10.8 ft., scribes CE 1/16 S31 BT RS707, visible on partially closed face, location tag on SW side.

OSBF Survey hub (31CW-7) bears N87° 37"W 2.40 ft.; in place. Corner falls on Ridge top, S52°E by N52°W; in place.

RESTORED

Var. 21 $\frac{1}{2}$ ° East

Reset the 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY E 1/16 C-C S31 1966 RS707", 34 inches in ground, in mound of rock, and from which a:


37" Fir stump bears S67°W 10.7 ft. to face ; scribed CE 1/16 S31 BT.

Set 4" x 4" x 60" white painted Cedar post 1.5 ft. SE of corner pipe. Oregon State Forestry Department metal location poster on SW BT. Also poster on 30" Fir BT N29 $\frac{1}{4}$ °E 10.8 ft.

Dated June 29, 1976

Restored by C. Wayne Cook under my direction.  
C. Wayne Cook, Transitman

Present and witnessed by Keith D. Whitehead



BOOK 5