

CHAINS

(904)

T3N S13 / R5W S18

+ 4 notches on S. edge, from which:

(Jammed  
copy of pg 3  
1796)

Hemlock 24" dia. N 80° 30' E 63 lks. marked T3N R5W S17 BT

Hemlock 12" dia. S 43° 15' E 63 lks. marked T3N R5W S18 BT

Hemlock 36" dia. S 8° 15' W 60 lks. marked T3N R6W S13 BT

Hemlock 10" dia. N 2° 45' W 63 lks. marked T3N R6W S12 BT

✓ 22° 30' E BT'S + Post in good Condition.

Copied from A.A. Morrill, DCS, Field Book #1, Pages 30 + 31.

21 May 1969 W.B. Barber, Co. Surveyor

\* 905

July 1893: 1/4 Corner Common to Sec 7, T3N, R5W + Sec. 13, T3N, R6W  
A Hemlock post down & decayed from which;

Hemlock 10" dia. EAST 20 lks. marked 1/4 S BT

Hemlock 12" dia. N 38° 45' W 31 lks. marked 1/4 S BT

At the Corner I set a Cedar post 4" sq. 4 ft. long 2 ft. in  
ground, marked 1/4 S on W. Side in place of old post. Used  
same BT'S.

Copied from A.A. Morrill DCS, Field Book #1, Page 31.

21 May 1969, W.B. Barber, Co. Surveyor.

Washington County Surveyor Records

BOOK 5