

CHAINS RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 15 and 16, T1N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 15" Hem bears S67 $\frac{1}{2}$ E 22 lks.; missing, roots in place.
- 7" Hem bears S32W 73 lks.; now 18" badly rotted stub, scribe BT remaining on rotted lower face.

RESTORED

Var 21 $\frac{1}{2}$ R

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY  $\frac{1}{4}$  S15 S16 1969 RS707", 31 inches in ground, in mound of rock, and from which a:

- 16" Fir bears S39E 3.8 ft.; scribed  $\frac{1}{4}$  S15 BT.
- 14" Fir bears S40 $\frac{1}{2}$ W 17.0 ft.; scribed  $\frac{1}{4}$  S16 BT RS707.
- Top of Spur ridge bears South 35 ft., slopes S60W.

Set 4" x 4" x 50" white painted Cedar post 1.0 ft. SW of corner pipe. Oregon State Forestry Department metal location poster on 14" Fir BT.

Dated May 19, 1970

Restored by

Present and witnessed by Charles Curl  
Keith Whitehead  
Steve Ellis

REGISTERED  
OREGON  
LAND SURVEYOR

*Harold J. Russell*  
JULY 9, 1965  
HAROLD J. RUSSELL  
707