


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: NONE



Description of corner evidence found: NONE


SEE MAP B-985
 FOR REVISED CORNER
 POSITION 7-17-81
 Allan Duncan C.S.

Description of monument and accessories I established to perpetuate the original location of this corner

Set 2" x 30" galvanized iron Pipe flared at the bottom and a brass cap riveted on top, extending 4" above the ground.

Set steel posts with Forest Service signs 5.0ft west and 4.0ft south of monument.

Stamped disk



New Bearing trees as follows:

18" Spruce scribed "E 1/16 53 BT" N19°34'W 30.28 ft.

18" Spruce scribed "E 1/16 53 BT" N 85°15'E 47.16 ft.

Placed USFS Bearing Tree signs on each tree at breast height & facing monument.

Office of COUNTY SURVEYOR County of TILLAMOOK

State of OREGON, I hereby certify that the within instrument was filed in this office for record on the 16 day of JUNE, 1971, at 9 o'clock A.m., (signed)

[Signature]
 (COUNTY OFFICIAL)

by (DEPUTY)

REGISTERED
 OREGON
 LAND SURVEYOR

[Signature]
 JULY 12, 1963
 AUGUST C. GIERING
 608

BOOK 5

CLARK & GROFF ENGINEERS, INC.
 3276 COMMERCIAL STREET S. E.
 SALEM, OREGON

Form R6-7100-57 (9/66)

	BOOK 5	158	
--	--------	-----	--