


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Monument set by T.O. McCullough ORLS 650
April 22, 1970



Description of corner evidence found:

Found 2" x 30" iron pipe with brass cap marked
Found Bearing trees as found by
McCullough.

- 40" snag S 75° W 191.4 ft. - mark rotted off.
 - 15" spruce brs. S 14° W 16.5 ft - with healed face.
 - 18" fir brs N 62° E 4.0 ft - with healed face
 - 15" fir brs S 38 1/2° E 34.0 ft - with healed face
- All have tags. (1954)



Description of monument and accessories I established to perpetuate the original location of this corner

NONE

REGISTERED
OREGON
LAND SURVEYOR

August C. Giering
JULY 12, 1963
AUGUST C. GIERING
608

Office of County Surveyor County of TILLAMOOK
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 16 day of JUNE, 1971, at 9 o'clock A.M., (signed)
J. L. Conlin CS by _____
(COUNTY OFFICIAL) (DEPUTY)

BOOK 5

CLARK & GROFF ENGINEERS, INC.
3276 COMMERCIAL STREET S. E.
SALEM, OREGON

Form R6-7100-57 (9/66)