

# County Surveyor's Record, Tillamook County, Oregon

## CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 2 and 11, Township 5 South, Range 10 West, W.M., Tillamook County, Oregon.

### ORIGINAL

10" Hemlock corner tree (now 20" stump, bottom of face on North side, rest of face cut off when logged) from which a:

- 12" Hemlock bears N5°W 4 lks.; now badly rotted root crown.
- 10" Hemlock bears S6°E 7 lks.; now 8" badly rotted stub 6" high.

Note: All 3 trees grew on an uprooted Fir tree.

### RESTORED

Var 21 1/2°E

Set 1 1/2" x 6" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BAORD OF FORESTRY 1/4 S2 S11 1972 RS401", 5 inches in center of 20" Hemlock corner tree stump, and from which a:

- 8" Hemlock bears S70 1/2°E 63.5 ft. to face; scribed 1/4 S11 BT RS401.
- 6" Hemlock bears N24°E 11.5 ft. to face; scribed 1/4 S2 BT.

Set 4" x 4" x 50" white painted Cedar post 1.0 ft. SE of corner pipe. Oregon State Forestry Department metal location poster on 8" Hemlock BT.

Dated April 17, 1973

Restored by Keith Whitehead under my direction.  
Keith Whitehead

Present and witnessed by B. Henderson  
G. Kelley

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Richard A. Morris*  
OREGON  
MAY 10, 1957  
RICHARD A. MORRIS  
401