

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner has never been established

DIAGRAM K
CSNN 1/256
Section 6

Reference:

Plat dated July 1973 by
Timberland Services, Inc.
under my stamp.

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner

I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked:

T 6 S R 10 W
S 6
C-S-N-N
1/256
1973
RLS 942

By proportional measurement,
From which:

- 12" Spruce West 31.5 ft.
mkd "CSNN 1/256 S 6 BT"
- 16" Spruce N 41° W 67.9 ft.
mkd "SCNN 1/256 S 6 BT"
- A 2 ft. stream West 13 ft.

Corner falls in west edge of field; erected small stone mound.

Witnessed: E. R. Cook

Office of County Surveyor County of Tuamook
State of OREGON I hereby certify that the within instrument was filed in this office
for record of the 29th day of AUGUST, 1973, at 9¹⁵ o'clock A. m., (signed)
[Signature] by _____
(COUNTY OFFICIAL) (DEPUTY)

Set this 19th day of July 1973

239

BOOK 5 Edgar R Cook

TIMBERLAND SERVICES, INC.
P.O. Box 668 - Albany, Ore. 97321
Phone: 928-3539

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Kenneth M. Wightman
OREGON
JULY 17, 1970
KENNETH M. WIGHTMAN II
942