

County Surveyor's Record, Tillamook County, Oregon
County Surveyor's Record, Tillamook County, Oregon

CHAINS

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 2, 3, 34 and 35, T2&3N, R7W, W.M.,
Tillamook County, Oregon.

ORIGINAL

32" Hemlock (now a 32" uprooted stump scribe marks destroyed by fire)
from which a:

- 18" Hemlock bears N67°E 43 lks.; missing.
- 24" Hemlock bears S40°E 54 lks.; now a 28" stump with scribes visible.
- 30" Hemlock bears S72°W 15 lks.; now a 24" stump, face burnt out.
- 24" Hemlock bears N49°W 21 lks.; now a 30" rotted stump.

RESTORATION by L. W. Amort, August 15, 1952.

1½" x 36" galvanized iron pipe with 3" bronze cap 28" in ground. (in place)
from which a:

- 30" Fir stump bears N30°E 115.0 ft.; now 30" stump with scribes visible.
- 36" Fir stump bears N58½°W 40.9 ft.; now a 36" stump with scribes visible.
- 26" Fir stump bears S29°W 9.5 ft.; now a 26" stump with scribes visible.

REWITNESSED

Var. 21½°E

From above corner monument in mound of rock a:

- 9" Fir bears S4°E 9.9 ft. to face; scribed T2N R7W S2 BT.
- 7" Hemlock bears S55°W 21.3 ft. to face; scribed T2N R7W S3 BT.
- 9" Fir bears N78°W 20.3 ft. to face; scribed T3N R7W S34 BT RS 707..
- 6" Hemlock bears N80 3/4°E 14.4 ft. to face; scribed T3N R7W S35 BT.

4" x 4" x 60" white painted Cedar post 0.5 ft. N.W. of corner pipe.
Oregon State Forestry Department metal location poster on 9" Fir BT.

Dated December 16, 1974.

Rewitnessed by Steve Ellis under my direction.
Steve Ellis, Compassman

Present and witnessed by Terry Withrow

