

County Surveyor's Record, Tillamook County, Oregon
County Surveyor's Record, Tillamook County, Oregon

CHAINS
CHAINS

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 3, 4, 9 and 10, T2N, R7W, W.M.,
Tillamook County, Oregon.

ORIGINAL

Basalt stone 19" x 14" x 10" (reset on North edge of iron pipe
below, (in place) from which a:

- 8" Hemlock bears N29°E 56 lks.; missing.
- 40" Fir bears S69°E 14 lks.; now a 54" stump face unexposed.
- 13" Hemlock bears S55°W 12 lks.; missing.
- 15" Hemlock bears N75°W 69 lks.; now a root crown.

RESTORATION by L. W. Amort, August 15, 1952.

OSBF galvanized iron pipe with 3" bronze cap 36" in ground.
Placed corner stone on North edge of pipe (in place) from which a:

- 52" Fir stub bears N87°E 78.4 ft.; now a 52" stump with face burnt out.
- 50" Fir stump bears S63°W 31.5 ft.; now a 50" stump with scribes visible.
- 48" Fir stump bears N63°E 24.0 ft.; now 48" stump with scribes visible.

REWITNESSED

Var. 21½°E

From above corner monument in mound of rock, a:

- 6" Fir bears N23-3/4°W 16.4 ft. to face; scribed T2N R7W S4 BT RS 707.
- 7" Hemlock bears N89-3/4°E 5.4 ft. to face; scribed T2N, R7W S3 BT.
- 10" Hemlock bears S51½°W 29.2 ft. to face; scribed T2N R7W S9 BT.
- 8" Hemlock bears S11°E 22.3 ft. to face; scribed T2N R7W S10 BT.

Set 4" x 4" x 60" white painted cedar post 1.0 ft. NE of corner pipe.
Oregon State Forestry Department metal location poster on 6" Fir BT.

Dated December 16, 1974.

Rewitnessed by Steve Ellis under my direction.
Steve Ellis, Compassman

Present and witnessed by Terry Withrow

