


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate measurement I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked:

T 4 S R 8 W

N 1/16

S 2 | S 1

1977

RLS 1073

From Which,

23" Douglas Fir 146.80 feet, S 54° W
mkd "N 1/16 S 2" "B.T."

11" Bigleaf Maple 123.90 feet, N 51° E
mkd "N 1/16 S 1" "B.T."

I set a 6' steel fence post and land survey monument sign. All bearing trees have brass washers, attention signs, bearing tree tags and red painted bands.

Witness: Monte Cook

See map B.764

D. Mike Jackson
Engineering Technician

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Kenneth M. Wightman

OREGON
JULY 17, 1970
KENNETH M. WIGHTMAN II
942

Office of County Surveyor County of Tillamook
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 8th day of AUGUST, 1977

[Signature]
(COUNTY OFFICIAL)

by County Surveyor
(DEPUTY)

Form R6-7100-57 (9/71)

Book 6 pg 25

TIMBERLAND SERVICES, INC.
1010 Airport Road P. O. Box 668
Albany, Oregon 97321
Telephone (503) 826-9404
LAND SURVEYING - ENGINEERING
LAND USE PLANNING - ROADS
FORESTRY CONSULTING

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Edgar R. Cook

OREGON
JULY 30, 1976
EDGAR R. COOK
1073