


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

There is no record of this corner legally being set.



Description of corner evidence found:

None

*FOR RESET OF THIS CORNER  
2/13/81  
ALSO*

Description of monument and accessories established to perpetuate the original location of this corner:

At proportionate measurement I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brass cap riveted to the top marked:

T 4 S    R 8 W  
S 1/16  
S 3 | S 2  
1977  
RLS 1073

From Which I marked a,  
22" Alder N 83° W, 3.9 feet Faced & Scribed  
26" Douglas Fir N 72° E, 47.3 feet  
15" Alder N 20° W, 16.9 feet Bark Scribed

I set a 6' steel fence post with land survey signs. All bearing trees have brass washers; attention signs, bearing tree tags and red painted bands.

Witness: Marvin Kirk

*See map B-764*

D. Mike Jackson  
Engineering Technician

Office of COUNTY SURVEYOR County of TILLAMOOK  
State of OREGON, I hereby certify that the within instrument was filed in this office  
for record on the 04 day of AUGUST, 1977  
[Signature] by COUNTY SURVEYOR  
(COUNTY OFFICIAL) (DEPUTY)

REGISTERED PROFESSIONAL LAND SURVEYOR

Kenneth M. Wightman  
OREGON  
JULY 17, 1970  
KENNETH M. WIGHTMAN II  
942


REGISTERED PROFESSIONAL LAND SURVEYOR

Edgar R Cook  
OREGON  
JULY 30, 1975  
EDGAR R. COOK  
1073

Form R6-7100-57 (9/71)

*Book 6*

*Pg 36*



TIMBERLAND SERVICES, INC.  
1010 Airport Road P. O. Box 666  
Albany, Oregon 97321  
Telephone (503) 926-0404  
LAND SURVEYING - ENGINEERING  
LAND USE PLANNING - ROADS  
FORESTRY CONSULTING