

County Surveyor's Record, Tillamook County, Oregon

CHAINS

SURVEY FOR JIM BETHELL

REESTABLISHMENT OF EXISTENT CORNER

West 1/4 Cor. Sec. 18, T. 4S. R.7 W.
East 1/4 Cor. Sec. 13, T. 4S. R.8W.
Wm. Mer.


Original Monument was GLO 1933 Brass Cap
Original Bearing Trees in 1933 were 24" Fir brs. N 78 Degrees E., 35 lks.
34" Fir brs. N 85 Degrees W., 65 lks.

The original brass capped pipe was inadvertently destroyed by logging.

Found 36" Fir with healed witness face, Found 34" fir stump with healed witness face, both these witness trees have U.S.F.S. location tags.

From these two trees which I determine to be the bearing trees set in 1933 I determined the original corner location by intersecting the respective distances noted.

At the original corner location I set a 1 1/2 " by 30 " brass capped iron pipe. Pipe has 5" flange at bottom. Pipe was filled with concrete and set in concrete, with 23" into the ground and 7" protruding. Brass cap is stamped as shown below.



Witnessed: Dennis Creel
11/26/79

REGISTERED
PROFESSIONAL
LAND SURVEYOR

George C. Griffith

OREGON
MAY 8, 1959
GEORGE C. GRIFFITH
223

BOOK 6