

County Surveyor's Record, Tillamook County, Oregon

CHAINS

6/21/80

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 1, 2, 11 and 12, T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 10" Cedar bears N45°E 23 lks.; now a 17" Cedar stump in place.
- 18" Fir bears S57°E 46 lks.; now a badly rotted 27" Fir stump with scribes "BT" visible.
- 10" Cedar bears S61°W 48 lks.; now a 12" Cedar stump with scribes "BT" visible.
- 24" Fir bears N23°W 34 lks.; now a badly rotted Fir stump with scribes "T3NR6W" visible.

RESTORATION by Oregon State Highway Department in 1940.

Found 3 dead bearing trees, from which set a 2"x48" galvanized iron pipe with brass cap. Also set a 4"x4" white guard post.

REWITNESSED

Var. 21 1/2°E

Above 2" iron pipe from which a:

- 9" Fir bears N61 1/2°W 3.2 ft. to face; scribed T3NR6W S2 BT.
- 10" Fir bears S60 1/2°W 5.6 ft. to face; scribed T3NR6W S11 BT.
- 9" Fir bears S76 1/2°E 23.8 ft. to face; scribed T3NR6W S12 BT RS1662.
- 10" Fir bears N71°E 28.7 ft. to face; scribed T3NR6W S1 BT.

OSHD 4"x4" white guard post in good condition 1.5 ft. SW of corner pipe. Oregon State Forestry Department metal location poster on 9" Fir BT S76 1/2°E.

Dated June 17, 1980

Rewitnessed by

*Steve Ellis*

Steve Ellis, Compassman

under my direction.

Present and witnessed by Othe] Hendrick

