

County Surveyor's Record, Tillamook County, Oregon

CHAINS

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 32, 33, 4 and 5, T3 & 4N, R6W, W.M., Tillamook and Clatsop Counties, Oregon.

ORIGINAL

Post (missing) from which a:

- 12" Fir bears N70°E 31 lks.; missing.
- 24" Hemlock bears S60°E 50 lks.; now a very rotted Hemlock stub.
- 36" Fir bears N5°W 30 lks.; missing.
- 10" Fir bears S85°W 34 lks.; missing.

RESTORATION by Oregon State Highway Department, 1942,

Found three dead bearing trees with scribing and set a 2"x48" galvanized iron pipe with brass cap.

Also set 4"x4" white guard post (in place) 2.0' Southwest of corner pipe.

REWITNESSED

Var. 21½°E

Above 2" iron pipe 8" above ground from which a:

- 14" Fir bears N6°E 18.5 ft. to face; scribed T4NR6W S33 BT RS1662.
- 14" Hemlock bears N57°W 62.9 ft. to face; scribed T4NR6W S32 BT.
- 10" Fir bears S3°W 23.9 ft. to face; scribed T3NR6W S5 BT.
- 22" Alder bears S69½°E 66.3 ft. to face; bark scribed T3NR6W S4 BT.

Oregon State Forestry Department metal location poster on 14" Fir BT.

Dated November 4, 1980

Rewitnessed by Terry Withrow under my direction.
Terry Withrow, Transitman

Present and witnessed by Andrew Casey.

