

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One-Quarter corner common to Sections 1 and 2, T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing). from which a:

30" fir bears N67°W 5 lks.; now a 30" rotted fir stump with axe marks visible.
8" cedar bears S88°E 28 lks.; now a 12" cedar uproot with scribes visible.

RESTORATION by OSHD, 1941.

Found stumps of both bearing trees with portions of blaze remaining.
Set 2" x 48" galvanized iron pipe (in place).
Set 4" x 4" white guard post (in place).
Did not scribe BT's.

REWITNESSED

VAR. 21½°E


Above mentioned 2" x 48" pipe, from which a:

14" fir bears N65°E 7.2 ft. to face; scribed 1/4 S1 BT.
9" fir bears N63½°W 23.2 ft. to face; scribed 1/4 S2 BT.

Oregon State Forestry Department metal location poster on 14" fir BT N65°E 7.2'.

Dated May 3, 1983.

Restored by _____ ~~under my~~ direction.



Present and witnessed by S. Ellis.

O. Hendrick.