

REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

One quarter corner for Section 27 (East side), T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL By Samuel D. Snowden, August 10, 1857.

Post; missing.

32" Hemlock bears S67°E 42 lks.; missing.
16" Hemlock bears S75°W 20 lks.; missing.

RESURVEY by Henry Meldrum, June 16, 1884.

NOTE: Meldrum did not find Snowden's point when completing the survey of this township.

Post on top of spur, slopes SW; post missing, spur in place.

5" Hemlock bears S45°E 42 lks.; missing.
24" Hemlock bears N30°W 29 lks.; now a rotted mound, no scribes visible.

RESTORATION by Richard A. Morris, LS401, February 19, 1959 (Book 1, page 387, Tillamook County Records).

1 1/2"x36" Galvanized iron pipe with 3" bronze cap, 30" in ground, in mound of rock; in place.

14" Hemlock bears N40°W 1.9 ft.; now a 15"x4ft. high badly rotted stump with portions of scribes 1/4 S27 BT RS401 visible.
4"x4"x54" white painted Cedar post bears SE 1.3 ft.; in place.

REWITNESSED July 28, 1987 Var. 21 1/2°E

From above pipe with marks "LS1998 1987" added, and from which a:


14" Hemlock bears N28°W 22.0 ft. to face; scribed 1/4S27BT.
13" Hemlock bears N59°E 10.4 ft. to face; scribed S26BT.

Metal location poster on new BTs.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by Clifford R. Foster

Rewitnessed by David B. Buchholz under my direction.
David B. Buchholz, Survey Crew Chief



Anthony J. Kosterman



BOOK 6

334