

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

Line tree corner common to Sections 6 and 7, T3S, R7W, W.M.,
Tillamook County, Oregon.

ORIGINAL by Frank H. Sharp, June 29, 1894.

60" Fir with 2 notches on East and West sides bears S89-54W
8.90 chains from the 1/4 corner for Section 6 and 7; now
a 68" stump, in place, with 2 notches on East and West sides,
exposed 1 notch on either side.

RESTORED May 5, 1988

Var. 21 1/2 E

Set 5/8"x36" Steel rebar with yellow plastic cap marked "LS1998",
34" into center of stump, and from which a:

28" Hemlock bears N12W 15.8 ft. to face; scribed WPS6BT.

23" Hemlock bears S85W 29.2 ft. to face; scribed WPS7BT.


Metal location poster on BTs.

3/4" brass washer marked "LS1998" nailed to face of BTs.

Present and witnessed by Clifford R. Foster.

Restored by David B. Buchholz under my direction.

David B. Buchholz, LS2272



Anthony J. Kosterman

