REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

Section corner common to Sections 21, 22, 27 and 28, T2S, R7W, W.M., Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, July 13, 1891.

Post; missing.

- 12" Hemlock bears S70E 25 lks.; now a 10"x4 ft. high badly rotted stub with portions of scribes 7 BT visible.
- 26" Larch bears S27W 19 lks.; now a 26"x2 ft. high badly rotted stub with axe work visible.
 - 6" Hemlock bears N29W 49 lks.; missing.
- 12" Hemlock bears N71 3/4E 93 lks.; missing.

RESTORATION by Louis W. Amort RE2311 January 29, 1952 (Book 2, page 123, Tillamook County Records).

- 1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in ground; under 4 ft. diameter fir log; in place 34" in ground, I notched the log to expose the pipe.
 - 60" Fir stub bears N53W 38.2 ft.; now a 49" badly rotted stump with scribes S21 BT 2311 visible.
 - 30" Fir stub bears S84E 63.0 ft.; now 22" badly rotted with scribes T2S R7S S27 BT visible.
 - 64" Fir snag bears N18E 45.7 ft.; now a 54" burnt and badly rotted stump with upper portion laying alongside, no face visible.

REWITNESSED October 28, 1988

Var. 21 1/2E

From the above pipe with marks "LS1998 1988" added, and from which a:

- 15" Fir bears N14 1/2W 21.6 ft. to face; scribed T2SR7WS21BT.
- 17" Fir bears N78E 5.0 ft. to face; scribed T2SR7WS22BT.
- 10" Fir bears S30E 31.4 ft. to face; scribed T2SR7WS27BT.
- 17" Fir bears S44W 19.0 ft. to face; scribed T2SR7WS28BT.

Metal location poster on new BTs. 3/4" brass washer marked "LS1998" nailed to face of new BTs. Present and witnessed by Clifford R. Foster.

Rewitnessed by David B. Buchholz under my direction.

David B. Buchholz, LS2272

PROFESSIONAL LAND SURVEYOR

OREGON

OREGON

JULY 10, 1998

ANTHONY I. KLOSTERMAN

1998

4907 Third St. Tillamook, Oregon 97141

