


TILLAMOOK COUNTY SURVEYORS OFFICE

1/4 Corner Common to sections 10 & 15 T.3N.,R.8W.,W.M.



I set a 10" concrete cylinder around found O.S.B.F. 1 1/2" iron pipe with 3" brass cap set in 1952, (see CS rewitness book 2 page 192).

I set a 72" hat section post 1.5' North and and affixed a yellow Tillamook County Corner tag.

History of found monument

I found this monument to be as described in the above said rewitness; However, the original distances recorded as follows:

20" Fir N.45*E. 10lks (should be N.45*E. 15lks according to microfilm copies of original field notes in surveyors office); now 24" rotten stub 4' high fits original bearing and distance.

4" vine maple S.41*W. 10lks (should be S.41*W. 15lks according to microfilm copies of original field notes in surveyors office); now missing, clump of saplings in place.

8" Alder N.72*W. 5.00'; now 13" alder with yellow corner tag at position stretched scribing visible.

8" Alder N.65*30'E. 22.5'; now 11" alder with yellow corner tag at position, stretched scribing visible.

10" Alder with O.S.B.F. metal location poster N.14*W. 12 ft.; now 17" alder with tag .

Monument location

This corner is located approximately 250' south of a gravel logging road which also serves as a driveway to some cabins farther up the road.

In the presence of Dan McNutt and Al Dvorak

February 1989

Title Allen E. Duncan, C.S.



BOOK 6 394