

REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

One quarter corner common to Sections 27 and 28, T2S, R7W, W.M.,
Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, July 13, 1891.

Post; missing.

30" Fir bears West 15 lks.; now a 34"x7 ft. high rotted stump
with edges of the face visible.

36" Fir bears S52 3/4E 82 lks.; now a 44"x5 ft. high rotted
stump, exposed lower face with portions of scribes and
chaining notch.

RESTORATION by Louis W. Amort RE2311, December 31, 1951 (Book 2,
page 103, Tillamook Co. Records.)

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in
ground, in mound of stone; in place, flush with ground.
Pipe was covered by a 3 1/2 ft. Fir log with an X at the
corner point. I notched the log to allow access to the
pipe.

88" Fir stump bears N88E 83.0 ft.; now 3 ft. high, badly
rotted with scribes 1/4 S27 BT visible.

48" Fir stump bears S76 1/2W 18.5 ft.; now rotted with
scribes 1/4 S28 2311 visible.

REWITNESSED March 8, 1989

Var. 21 1/2 E

From above pipe with marks "LS1998 1988" added, a:

11" Fir bears N34W 17.3 ft. to face; scribed 1/4S28BT.

8" Fir bears N58E 14.2 ft. to face; scribed 1/4S27BT.


Metal location poster on new BTs.

Also 1951 metal location poster on 34" Fir stump BT.


3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by Clifford R. Foster.

Rewitnessed by David B. Buchholz under my direction.
David B. Buchholz, LS2272



Anthony J. Klosterman



4907 Third St.,
Tillamook, Oregon 97141



BOOK 6 400