

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

Line tree corner common to Sections 11 and 12, T3N, R8W, W.M.,
Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, August 25, 1893.

38" Fir with bears S00-01E 11.67 chains from the 1/4 corner for
Sections 11 and 12; now a 46" stump with 2 notches on North
and 1 notch on South, exposed one notch on North.

RESTORED March 20, 1989

Var. 21 1/2 E




Set 5/8"x36" Steel rebar with yellow plastic cap marked "LS1998",
25" into center of stump, and from which a:

19" Hemlock bears S10E 13.2 ft. to face; scribed WPS12BT.
26" Hemlock bears N89W 15.4 ft. to face; scribed WPS11BT.

Metal location poster on BTs.

3/4" brass washer marked "LS1998" nailed to face of BTs.
Present and witnessed by Clifford R. Foster.

Restored by David B. Buchholz under my direction.
David B. Buchholz, LS2272



4907 Third St.,
Tillamook, OR 97141