

TILLAMOOK COUNTY SURVEYORS OFFICE

Witness Corner 2 Chains West  
of  
Section Corner common to Sections 25 & 36 T.4S.,R.11W.,W.M.  
and  
Sections 30 & 31 T.4S.,R.10W.,W.M.

T 4 S  
R11W|R10W  
S25|S30  
----+----WC  
S36|S31  
1924

I found a 2 1/2" U.S. General Land Office brass cap on a 1 1/2" iron pipe in a mound of stone and chunks of concrete, as described in Tillamook County Surveyors Book 4511 at page 21. I encase the found iron pipe with brass cap in an irregular mass of concrete.

History of found Monument

I found this monument to be as reported in the above said book and page, and maps of reference to be as follows:

B-513	1963	John A. Bond	PE 3416
B-566	1968	John L. Carlich	LS 287
A-719	1957	John L. Carlich	LS 287

New Accessory

\*84" steel hat section post 1.6' North.

\*indicates yellow metal Tillamook County location tag attached.

Monument Location

This corner is located on a flat, sandy area on Nestucca spit ( AKA Bob Straub State Park ).

In the presence of Dan McNutt & Al Dvorak

February 1990

Title

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Allan E. Duncan, C.S.*

OREGON  
JULY 14, 1967  
ALLAN E. DUNCAN  
793

