

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON --DEPARTMENT OF FORESTRY

East One Sixteenth corner common to Sections 13 and 24, T2N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Oregon State Board of Forestry Pipe with cap, 1968 (missing in land clearing excavation) from which a:

- 7" Spruce bears N14 3/4°W 91.2 ft.; now 9", scribes E 1/16 S13 BT visible on partially closed face.
- 10" Spruce bears N67 3/4°E 126.9 ft.; now 10" uproot, not in place, removed in road construction.
- Miami county road centerline bears N79°42'E 161.9 ft.; in place.
- Miami county road centerline bears S1°06'W 132.1 ft.; in place.

RESTORED

Var. 21 1/2° East

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY E 1/16 S13 S24 1976 RS 707" 33 inches in ground, in mound of rock, and from which a:

9" Spruce bears N58°E 55.5 ft. to face; scribed E 1/16 S13 BT RS 707.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. SE of corner pipe.
Oregon State Forestry Department metal location poster on 9" Spruce N58°E 55.5 ft.

Dated November 17, 1976.

Restored by Keith D. Whitehead under my direction.
Keith D. Whitehead, Transitman

Present and witnessed by Greer Kelly

