

# County Surveyor's Record, Tillamook County, Oregon

CHAINS

## RESTORED CORNER FOR STATE OF OREGON -- DEPARTMENT OF FORESTRY

Section corner common to Sections 11, 12, 13 and 14, T3S, R9W, W.M., Tillamook County, Oregon.

### ORIGINAL

6" Alder corner tree ( now rotted root crown) from which a:

10" Alder bears N30°E 13 lks.; missing.

8" Alder bears S80°E 17 lks.; missing.

12" Alder bears S50°W 10 lks.; now 18" uproot axe work around rotted out face.

12" Alder bears N67°W 15 lks.; missing.

Note: On April 25, 1963, R. Morris and myself found this corner and saw scribing on the corner tree. We axed a crusier mark on the YLMP tree N11 E 0.8' from the corner point found in place.

### RESTORED

Var. 21½° E

Set 1½' x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3S R9W S11 S12 S13 S14 1979 RS707", 34 inches in ground, in center of original corner tree remains and from which a:

15" Alder bears S73°W 45.9 ft. to face; bark scribed T3S R9W S14 BT.

30" Alder bears N59°W 46.2 ft. to face; bark scribed T3S R9W S11 BT.

18" Alder bears N79°E 56.2 ft. to face; bark scribed T3S R9W S12 BT RS707.


18" Alder bears S82°E 12.8 ft. to face; bark scribed T3S R9W S13 BT.

Top of cliff, 30' high, bears South 12 feet.

Set 4" x 4" x 48" white painted Cedar post 1.0 ft. SW of corner pipe. Oregon State Forestry Department metal location poster on 15" Alder N11°E 0.8 ft.

Dated May 1, 1979

Restored by



Present and witnessed by R.A. Morris