

Tillamook County

T 2 N, R 10 W.M.

Corner Code No.

Segregated Surveys:

Name: Subdivision of Section 23

Corner No.: 1/4 corner 23/26

DLC, HES, Tract, Mining Claim, Indian Allotment, Federal Reserve, Townsite.

1. History of Corner Establishment and Subsequent Restoration:

1873 C.J. Handley (G.L.O.), set post for 1/4 corner and 2 B.T.'s

Hemlock, 16" Dia., Bears S. 3°E, Dist. 9 Links. Hemlock, 5" Dia., Bears N.19°W, Dist. 17 Links.

1947 W.A. Markham found original 16" Hemlock living w/ Scribing visable No evidence of 5" Hemlock Set 1" I.P.

2. Description of Evidence Found:

Found: Iron Pipe 1"x 24"


Found original 16" Hemlock. B.T. is now stump with scribing still visable.

3. Describe Monument, Accessories and Corollary Data to Perpetuate this Corner Location. Diagram corner and indicate meridian and reference to map of record. Surveyor's Field Book No. Page No. Date of work June 18, 1979

1/4 Corner 23 Restored. Set Crown Zellerbach Brass Cap in 2" x 36" Iron Pipe with 4" x 4" White painted Cedar post 2.0' North

8" Hemlock N 34° 49' E 22.50' with B.T. tag and YMLP

14" Hemlock S 26° 17' E 29.98' with B.T. tag and YMLP



Oregon Coordinate System: Zone, Y Order Accuracy. Derived From:


Pin Pointed on Photo No. Date. Located at.

SURVEYOR'S CERTIFICATE

This corner record correctly represents work performed by me or under my direction in compliance with the provisions of ORS 209.250, Laws of 1956. Date 7/25/79

Signature Colin H. Handforth

Certificate No. 1205



826

BOOK 6

67

See map B-844

EXHIBIT E