

# County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR PUBLISHERS PAPER CO.

Northeast 1/16 corner for Section 6, T3S, R8W, W.M., Tillamook County, Or.

Original: 1/12"x36" Galvanized iron pipe with Brass Cap marked Oregon State Board of Forestry NE 1/16 S6, 1967 RS 707; found lying near corner position.  
32" Hemlock N15° W 25.6 feet; now 34" with partially closed face.  
24" Hemlock S68 1/2° W 22.4 feet; now missing in logged area.  
10" Cedar S8° E 5.6 feet now 10" stub in place.  
White Painted Cedar Post S.E. 1.0 feet, now rotted off.

RESTORED: Set above iron pipe at recorded bearing and distance from 34" Hemlock and 10" Cedar stub, from which a:  
27" Hemlock Stump bears S87 3/4° W 17.6 feet to face; scribed N.E. 1/16 S6 BT RS 1098

Dated : November 28, 1979

Restored by: Boyce S. Henderson , under the direction of C. Wayne Cook

Present and witnessed by: J.D. Dixon

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*C. Wayne Cook*

OREGON  
JULY 22, 1977  
C. WAYNE COOK  
1098