

County Surveyor's Record, Tillamook County, Oregon

CHAINS

D-151

GOVERNMENT CORNER RESTORATION

POLK COUNTY, OREGON

At the Section corner common to Sections 18 and 19 in Township 6 South, Range 8 West of the Willamette Meridian. Said corner being on the East boundary of Section 24 in Township 6 South, Range 9 West. I find a stone, 21" X 12" X 8", in mound of stone. In place of said stone I set a 1 1/2" X 30" iron pipe with 2" Polk County Brass Cap marked: "S 24, T.6S., R.9W., S 18, S 19, T.6S., R.8W., 1977". I reset said stone 1' S.E. and rebuilt stone mound. Also found the following stumps agreeing well with 1887 GLO field notes: 30" (24") FIR STUMP, N.10°E., (N.09°E.), 21.12 feet to face, scribes "S 18, SR 8 W, GRIR" visible. 32" (30") FIR STUMP, S.72°E. (S.75°E), 9.9 feet to face, scribes "S 19, R.8W., GRIR" visible. I marked the following new trees: 16" D. FIR, N. 42 1/2°E., 64.3 feet to face, 65.0 feet to center, marked: "T.6S., R.8W., S. 18 BT." 12" D. FIR., S.56°E., 42.9 feet to face, 43.4 feet to center, Marked: "T.6S., R.8W., S. 19 BT." 9" D. FIR, S.64°W., 17.4 feet to face, 17.8 feet to center, Marked: "T.6S., R.9W., S 24 BT." MAG. VAR. 20°E.

7-11-77

Witness: R. Schulson
D. Shackelford

659 658
T11 13 | 18 Polk
29 | 19 Polk
Lincott

REGISTERED
PROFESSIONAL
LAND SURVEYOR

C. Ralph Planchon

OREGON
JULY 14, 1927
C. RALPH PLANCHON

BOOK 6