

Remonumentation of Certain Original Corner Points,
T. 4 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 4 S R 9 W

½
S 34 | S 35
1978

Reset iron pipe and set a 5 ft. steel fence post alongside iron post.

The ¼ sec. cor. of secs. 26 and 35, perpetuated and recorded by Leonard Whitmore, Deputy County Surveyor, in 1963, monumented with an iron pipe, 1 in. diam., firmly set, projecting 20 ins. above ground, from which the remains of the original bearing trees:

A decayed fir snag, size indeterminate, bears N. 69° E., 51 lks. dist., no marks visible. (Record, N. 63° E.)

A decayed alder snag, 24 ins. diam., bears S. 11° E., 61 lks. dist., with scribe mark S visible on overgrowth.

and a bearing tree mkd. by Whitmore

A spruce, 38 ins. diam., bears N. 44° E., 71 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 4 S R 9 W

¼ S 26
S 35
1978

from which a new bearing tree

An alder, 17 ins. diam., bears S. 75° W., 42 lks. dist., mkd. ¼ S35 BT on bark.

Reset iron pipe and set a 5 ft. steel fence post alongside iron post.

The ¼ sec. cor. of secs. 22 and 23, perpetuated and recorded by Leonard Whitmore, Deputy County Surveyor, in 1961, monumented with an unmarked fir post, 4 ins. square, firmly set, projecting 30 ins. above ground, and in a mound of stone, 3 ft. base, 1 ft. high, from which the remains of the original bearing trees:

A decayed fir snag, size indeterminate, bears S. 71½° E., 126 lks. dist., with fragmentary scribe marks visible on open blaze.

A decayed fir snag, size indeterminate, bears S. 86° W., 154 lks. dist., no marks visible.

and bearing trees mkd. by Whitmore

A fir, 19 ins. diam., bears S. 5° E., 38 lks. dist., with healed blaze.