

County Surveyor's Record, Tillamook County, Oregon

CHAINS

6/26/80

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Quarter corner common to Sections 11 and 14, T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a;

48" Fir bears N70°E 191ks.; now a badly burnt uprooted tree with axe work visible on pieces of wood.

24" Hemlock bears S12°30"E 47 lks.; now a badly rotted 22" Hemlock, stump with scribe visible on piece of wood, also half of "X" chopped on rotted portion of tree trunk.

RESTORED

Set 1 1/2 "x 3/4" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R6W 1/4 S11 S14 1980 RS1662", 35 inches in ground, from which a:

20" Fir bears S63 1/2°E 17.5 ft. to face; scribed 1/4 S14 BT RS1662.


13" Fir bears N74°W 21.0 ft. to face; scribed 1/4 S11 BT.

Set 4"x4"x60" white painted Cedar post 1.0 ft. NE of corner pipe.  
Oregon State Forestry Department metal location poster on 20" Fir BT S63 1/2°E.

Dated June 5, 1980

Restored by Steve Ellis under my direction.  
Steve Ellis, Compassman

Present and witnessed by Othel Hendrick



*Loren R. Steele*  
OREGON  
JULY 14, 1978  
LOREN R. STEELE  
1662