

County Surveyor's Record, Tillamook County, Oregon

CHAINS

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 6, 7, 1, and 12, T3N, R5 & 6W, W.M., Tillamook and Washington Counties, Oregon.

ORIGINAL

4" Cedar tree (missing) from which a:

- 30" Fir bears N6°W 20 lks.; now a 26" rotted fir stump.
- 24" Fir bears S5°E 12 lks.; missing.
- 14" Fir bears S5°W 15 lks.; now a badly rotted fir rootwad with portions of face and axework visible.
- 6" Cedar bears N85°E 15 lks.; missing.

RETRACEMENT by Lincoln E. Wilkes, September 1892, Government Contract #598.

Found 4" Cedar tree from which a:

- 24" Fir bears N22°W 20 lks.; missing.
- 16" Fir bears S44°E 15 lks.; missing.
- 16" Fir bears S20 1/2°W 12 lks.; missing.
- 8" Cedar bears N89°E 18 lks.; missing.

RESTORATION by Oregon State Highway Department in 1941,

Found a 1 1/2" iron pipe set in hole of a 12"-18" uprooted, badly burned cedar. Replaced pipe with a 2"x48" galvanized iron pipe with brass cap. Also set 4"x4" white guard post.

REWITNESSED Var. 21 1/2°E


Above 2" iron pipe from which a:

- 12" Fir bears S72 3/4°E 12.7 ft. to face; scribed T3NR5W S7 BT.
- 20" Fir bears N74°W 43.4 ft. to face; scribed T3NR6W S1 BT RS1662.
- 5" Fir bears S82 3/4°W 43.8 ft. to face; scribed T3NR6W S12 BT.
- 21" Fir bears N79 1/2°E 42.6 ft. to face; scribed T3NR5W S6 BT.

OSHD 4"x4" White guard post in good condition 1.5 ft. East of corner pipe. Oregon State Forestry Department metal location poster on 12" Fir BT.

Dated June 17, 1980

Restored by Steve Ellis under my direction.
Steve Ellis, Compassman



Present and witnessed by T. Withrow
O. Hendrick

