

Remonumentation of Certain Original Corner Points,
T. 6 S., R. 10 W., Willamette Meridian, Oregon

CHAINS

A spruce, 55 ins. diam., bears N. 15° W., 25 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 6 S R 10 W
½
S 15 | S 14
1979

Reset iron pipe alongside iron post.

The ¼ sec. cor. of secs. 10 and 11, determined at record bearing and distance from the remains of the original bearing trees:

A hemlock, 27 ins. diam., bears S. 25° E., 23 lks. dist., with fragmentary scribe marks visible on partially open blaze.

A root hole, bears S. 32° W., 28 lks. dist., with a down fir alongside, 30 ins. diam., no marks visible.

and a bearing tree mkd. by Leonard Whitmore, Deputy County Surveyor, in 1967

A spruce, 35 ins. diam., bears N. 39° W., 46 lks. dist., with scribe marks S10 BT visible on partially open blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T 6 S R 10 W
½
S 10 | S 11
1979

from which a new bearing tree

A hemlock, 25 ins. diam., bears N. 88° W., 44 lks. dist., mkd. ½ S10 BT.

The cor. of secs. 2, 3, 10, and 11, monumented with an iron pipe, 1 in. diam., firmly set, projecting 20 ins. above ground, from which the remains of the original bearing trees:

A hemlock, 12 ins. diam., bears N. 80° E., 11 lks. dist., with axe marks visible on open and decayed blaze. (Record, N. 74° E.)

A decayed spruce stump, size indeterminate, bears S. 55° E., 11 lks. dist., no marks visible.

A hemlock, 27 ins. diam., bears S. 49° W., 23 lks. dist., with healed blaze.

A decayed fir stump, 24 ins. diam., bears N. 39° W., 10 lks. dist., with fragmentary scribe marks visible on opened blaze.