

# County Surveyor's Record, Tillamook County, Oregon

CHAINS

## RESTORED CORNER FOR CROWN ZELLERBACH CORPORATION

SECTION CORNER common to Sections 29,30,31,32,T2S,R9W W.M.,Tillamook County, Oregon.

### ORIGINAL:

Post (now missing) from which a;

24" Hemlock bears N35°W 28 lks. ( now badly rotted stump )on old windfall, no marks visible).

24" Hemlock bears N55°E 19 lks. ( now badly rotted windfall)

16" Spruce bears S44°E 42 lks. ( now 38" stump, exposed scribe " T2S S32" ).

16" Hemlock bears S69°W 15 lks. ( now missing ).

80 lks. creek bears South 2 ch. ( in place ).

### RESTORATION by Hays 1888:

Post ( now lying on ground along side of 1 1/4"iron pipe, not of record ).

20 " Hemlock bears S7°W 48 lks.( now badly rotted stump, no marks visible ).

### Restored:

Set 2"x36" Iron pipe, with 3" Crown Zellerbach brass cap marked "T2S R9W S30 S29 S31 S32 1981 RS 1098", over 1 1/4" Iron pipe, from which;

13" Hemlock bears N20°E 66.1 ft. to face, scribed "T2SR9WS29 BT"

12" Hemlock bears N82°W 40.0 ft. to face, scribed "T2SR9WS30 BT"

11" Hemlock bears S51°W 44.7 ft. to face, scribed "T2SR9WS31 BT RS1098."

11" Hemlock bears S62°E 37.8 ft. to face, scribed "T2SR9WS32 BT"  
2"x2"x40" squared post N.W. 1.0 ft.

All new BT's have a yellow metal location poster, yellow metal " BEARING TREE, DO NOT CUT " poster, and a 3/4" Brass disk "RS1098" nailed to face.

Dated February 20, 1981

Restored by C.Wayne Cook

Present and witnessed by Boyce S.Henderson

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*C. Wayne Cook*

OREGON  
JULY 22, 1977  
C. WAYNE COOK  
1098