

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 2, 3, 34, and 35, T3 & 4N, R6W, W.M., Tillamook and Clatsop Counties, Oregon.

ORIGINAL

Post (missing) from which a:

24" Hemlock bears N25°E 8 lks.; destroyed by logging.

24" Hemlock bears S75°E 17 lks.; destroyed by logging.

12" Hemlock bears S73°E 86 lks.; now roots in place.

24" Hemlock bears N15°W 7 lks.; now badly rotted root crown.

1 lk. creek bears West 19.8' crs. South; in place.

5 lk. creek bears S0°25'E 52.8' crs. East; in place.

4 lk. creek bears East 158.4' crs. NE; in place.

RESTORATION BY Oregon State Highway Department in 1941, set a 2" x 48" galv. iron pipe with a brass cap and a 4" x 4" white guard post; iron pipe and post were moved out of place by logging. Found rotted bottom of post 0.5' East of corner point.

Found Oregon State Forestry tag N15°E 12.8' dated May 7, 1959 on a dead willow uproot.

RESTORED

VAR. 21-1/2°E

Set 2" x 36" aluminum pipe with 3-3/4" aluminum cap marked "STATE OF OREGON DEPARTMENT OF FORESTRY T4NR6W T3N S2S3S34S35 1982 RS1662", 35 inches in ground, and from which a:

17" Fir bears N15°E 24.9 ft. to face; scribed T4NR6WS35BT.

11" Cedar bears N51°W 51.2 ft. to face; scribed T4NR6WS34BT.

15" Hemlock bears S31-1/2°W 66.7 ft. to face; scribed T4NR6WS3BT.

20" Fir bears S31°E 1.0 ft. to face; scribed T4NR6WS2BT.

Corner falls on East side of knob.

Laid highway iron pipe beside corner.

Set 4" x 4" x 60" white painted Cedar post NW 1.0 ft. from corner pipe. Oregon State Forestry Department metal location poster on 20" Fir BT.

Dated October 7, 1982

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Loren R. Steele*

OREGON  
JULY 14, 1978  
LOREN R. STEELE  
1662

Present and witnessed by S. Ellis

O. Hendrick