

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One Quarter corner common to Sections 9 and 16, T3N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

18" x 9" x 5" Basalt Stone; (missing) from which a:
20" Larch bears S40°W 32 lks.; now a 24" Noble Fir uproot with scribes visible.
20" Hemlock bears N42°W 46 lks.; missing.

RESTORATION by International Paper Company in 1957.

Set 1½" x 4' iron pipe; found laying in creek bottom; from which a:
30" Hemlock stump bears South 33.0 ft.; now S11°30'W 35.0' with yellow metal corner and tag.
53" Fir stump bears N58°E 35.0 ft.; now N58°E 41.9' with blaze.

RESTORED

Var. 21½°E



Set 2" x 36" aluminum pipe with 3-3/4" aluminum cap marked "STATE OF OREGON DEPARTMENT OF FORESTRY T3NR7W1/4S9S16 1983 RS 1662", 12 inches in ground, with magnet inside, in mound of rock, and from which a:

13" Alder bears S14°W 19.9 ft. to face; bark scribed 1/4 S16 BT.
8' x 9' x 7' boulder bears N1½°W 10.1 ft. to face; chiseled XB0.

Corner falls in 2' creek, Crs; west from east.

Set 4" x 4" x 60" white painted Cedar post South 9.5 ft. from corner pipe. Oregon State Forestry Department metal location poster on 13" Alder BT.

Dated August 22, 1983.



Present and witnessed by Steve Ellis
Othel Hendrick