

# County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 13 and 24, T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL by C.J. Handley, July 5, 1873:  
Post (missing) from which a:

20" Hemlock bears N15<sup>0</sup>W 20 lks.; missing.  
66" Spruce bears S50<sup>0</sup>E 15 lks.; now 74" stub, 12 feet high,  
face cut out, no scribing visible.

RESTORED

VAR. 21½<sup>0</sup>E

Set 1½" X 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY T1N R10W ¼ S13 S24 1984 RS  
1998", 34 inches in ground, in mound of rock, and from which  
a:

35" Hemlock bears N79<sup>0</sup>W 148.4 ft. to face; scribed ¼S13BT.  
5" Alder bears N26<sup>0</sup>E 16.0 ft. to bark scribes ¼S13BT.

Set 4" X 4" X 60" white painted Cedar post N53<sup>0</sup>W 2.4 ft. from  
corner pipe.

Oregon State Forestry Department metal location poster on original  
66" Spruce BT.

Also poster on 5" Alder BT.

Dated April 25, 1984

Restored by:

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Anthony J. Klosterman*

OREGON  
JULY 16, 1982  
ANTHONY J. KLOSTERMAN  
1998

Present and witnessed by David B. Buchholz

