

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner (common to) Sections 21 and 28, T3N, R7W,
W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 24" Hemlock bears S10°E 34 lks.; missing.
- 12" Hemlock bears N34°E 39 lks.; missing.
- 2 links brook bears East 3.11 chains in place.
- 8.11 chains East, leave Salmonberry river which runs S60°W;
in place.
- 10.11 chains East, line touches the Salmonberry river which
comes from S60°E; in place.
- Original line blaze bears West 93' on 30" cedar stump.
- 1.89 chains West line touches bend of Salmonberry river
which comes from S60°E and runs SW; in place.

RESTORED

VAR 21½°E


Set 2" x 36" aluminum pipe with 3 3/4" cap marked STATE OF
OREGON DEPARTMENT OF FORESTRY T3N R7W ¼ S21 S28 1985
RS1662", 34 inches in ground, and from which a:

- 10" fir bears N3 3/4°E 32.8 ft. to face; scribed ¼ S21 BT.
- 15" fir bears S7½°W 19.0 ft. to face; scribed ¼ S28 BT.


Set 4" x 4" x 60" white painted cedar post SW 1.0 ft. from
corner (pipe). Oregon State Forestry Department metal
location poster on 18" alder S55°E 2.6'.

Dated: August 6, 1985

Restored by:



Loren R. Steele



Present and witnessed by: S. Ellis
O. Hendrick