

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 15, 16, 21, and 22, T3N, R6W, W.M.,
Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 60" fir bears N24°30'E 19 lks.; now a burnt out shell, scribes missing.
- 36" fir bears S80°20'E 46½ lks.; now a 37" stump with scribes T3NR6W S22 visible.
- 48" fir bears S23°W 29 lks.; now a burnt out shell, scribes missing.
- 22" hemlock bears N18°W 9 lks.; now a badly rotted uproot, scribes missing.

RESTORED

Set 2" x 36" aluminum pipe and magnet with 3 3/4" aluminum cap marked "STATE OF OREGON DEPARTMENT OF FORESTRY T3NR6W S15 S16 S21 S22 1986 RS1662," 34 inches in ground , and from which a:

- 14" fir bears N53½°E 12.7 ft. to face; scribed T3NR6W S15 BT.
- 13" hemlock bears N8½°W 5.4 ft. to face; scribed T3NR6W S16 BT.
- 21" fir bears S8°E 21.2 ft. to face; scribed T3NR6W S22 BT.
- 25" fir bears S66½°W 23.9 ft. to face; scribed T3NR6W S21 BT.


Set 4" x 4" x 60" white painted cedar post NW 1.0 ft. from corner pipe.
Oregon State Forestry Department metal location poster on 13" hemlock BT.

Dated July 17, 1986

Restored by



Present and witnessed by S. Ellis
G. Martin



Book 6 286