

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 15 and 16, T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post; found remains of squared off post under surface from which a:

50" fir bears S82°E 18 lks.; destroyed by railroad construction.

50" fir bears S18°W 11½ lks.; now 50" stump with scribes ¼S visible.

60" fir line tree bears north 0.34 chains; now a badly burned and rotted stump; in place.

RESTORED

Set 2" x 36" aluminum pipe and magnet with 3 3/4" aluminum cap marked "STATE OF OREGON DEPARTMENT OF FORESTRY T3NR6W ¼S15 S16 1986 RS1662," 35 inches in ground, and from which a:


14" fir bears N83°W 16.6 ft. to face; scribed ¼S16 BT.

22" fir bears N59°E 9.7 ft. to face; scribed ¼S15 BT.

Set 4" x 4" x 60" white painted cedar post SW 1.0 ft. from corner pipe.  
Oregon State Forestry Department metal location poster on 14" fir BT.

Dated July 24, 1986.

Restored by



*Loren R. Steele*



Present and witnessed by O. Hendrick  
G. Martin  
L. Fick

