

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

One quarter corner common to Sections 11 and 14, T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL by C.J. Handley, July 9, 1873.

Post in mound; missing.

4" Alder bears N30°E 7 lks.; missing.

5" Spruce bears S10°E 17 lks.; now root crown, in place.

RESTORATION January 14, 1889 (Book 10, Page 70, Tillamook Co. Records).

Post; missing.

16" Hemlock bears S75°E 32 lks.; now 37" with scribes BT 1/4 visible.

RESTORATION by W.E. Anderson August 22, 1949 (Book 1, Page 82, Tillamook Co. Records).

Spruce limb; missing.

18" Hemlock bears S38°W 19.2 ft.; now a badly rotted portion of uprooted root crown.

24" Hemlock bears S04°W 18.0 ft.; missing.

RESTORED

Var. 21 1/2°E

Set 1 1/2" X 30" aluminum pipe with 3 3/4" cap marked "STATE OF OREGON DEPARTMENT OF FORESTRY T1N R10W 1/4 S11 S14 1987 LS1998", 28 inches in ground, and from which a:

37" Hemlock (1889) bears S75°E 19.6 ft. to face; scribed 1/4S14BT (below old face).

20" Hemlock bears N22°E 58.9 ft. to face; scribed 1/4S11BT.


Set 4"X4"X60" white painted Cedar post N71°E 1.5 ft. from corner pipe.

Metal location poster on new BT.


Also poster on 37" Hemlock BT.

Dated April 13, 1987.

Restored by



Anthony J. Klosterman



Present and witnessed by David B. Buchholz
Clifford R. Foster